

Article 19: PAYG Capital - Highway Ford Explorer



- \$41,000 to replace existing 2005 Ford Explorer
 - **Frame is severely corroded and becoming structurally compromised**
 - Vehicle failed inspection this year
 - Used 24/7 by Highway Manager for emergency response and storm management



D
HOPKINTON
W

Article 19: PAYG Capital – Repair of Lake Maspenock Dam Gate

- \$110,000 for the replacement of the gate on the Lake Maspenock dam
- Will ensure DPW's management of the Lake's level to protect the dam, personal property on the Lake and downstream; control of weeds; and protecting the delicate ecosystem within the Lake



D
HOPKINTON
W

Article 19: PAYG Capital – Replacement of Hayden Rowe Drainage Pipe

- \$90,000 to design and construct a culvert to replace existing, failing culvert
- New culvert must be extended to accommodate road widening and new sidewalk

